

Flash Alert

Fractured Arm – Neachley BPS Neachley Borehole Maintenance - Incident

Incident Details		Contract Number: XXXX-XX
-------------------------	--	--------------------------

Date: 04.07.20	Scheme: Neachley Borehole Maintenance	On-Site Location: Access Road
----------------	---------------------------------------	-------------------------------

Incident Outline

The IP along with another member of his gang were tasked with moving some 150mm and 200mm temporary pipework (bagging) to a designated storage area on site. The two operatives had moved 6 lengths of pipe and were in the process of placing a further pipe into position when one of the operatives slipped and fell to the floor. The injured party continued to work for a short while before seeking medical advice and going to A&E for an X-ray where it was established that he had fractured his right lower arm.

Photographs



Photo 1: Pipe laydown area ready for collection



Photo 2: Other view of laydown area

Additional Information

- Works stopped and area fenced off
- Tool box talk held on slips & trips and a review of site practices underway
- Root Cause investigation underway

Immediate Action Required

- Flash Alert to be briefed to site teams
- A review of all access routes and work areas, to ensure they are compliant with OSS 100 Site Establishment & Maintenance
- Review of working areas to ensure any potential for slips/trips are addressed.
- Reinforce the 'Look after your mate' mantra.

Please ensure your teams are briefed on the above incident and resulting corrective actions.

Compiled By:	E.O'Connell/R Wladron	Title:	QES Advisor/Contrcts Manager	Date:	07/07/2020
Approved By:	N Harrison	Title:	Operations Manager	Date:	07/07/2020
Published By:		Title:		Date:	